



## P1316

SPRINGS

### Material

Stainless steel (EN10270-3, DIN 1.4310).

| Order No.      | d <sub>1</sub> | d <sub>2</sub> | l<br>±0.25 | For spring |
|----------------|----------------|----------------|------------|------------|
| P1316.10-12-10 | 10             | 12             | 10         | P1315.10-A |
| P1316.12-16-10 | 12             | 16             | 10         | P1315.10-B |
| P1316.15-17-15 | 15             | 17             | 15         | P1315.15-A |
| P1316.20-23-15 | 20             | 23             | 15         | P1315.15-B |
| P1316.15-17-20 | 15             | 17             | 20         | P1315.15-C |
| P1316.20-23-20 | 20             | 23             | 20         | P1315.15-D |
| P1316.30-34-15 | 30             | 34             | 15         | P1315.20-B |
| P1316.30-34-20 | 30             | 34             | 20         | P1315.20-D |
| P1316.20-23-25 | 20             | 23             | 25         | P1315.20-E |
| P1316.30-34-25 | 30             | 34             | 25         | P1315.20-F |
| P1316.25-28-15 | 25             | 28             | 15         | P1315.25-A |
| P1316.35-39-15 | 35             | 39             | 15         | P1315.25-B |
| P1316.25-28-20 | 25             | 28             | 20         | P1315.25-C |
| P1316.35-39-20 | 35             | 39             | 20         | P1315.25-D |
| P1316.25-28-25 | 25             | 28             | 25         | P1315.25-E |
| P1316.35-39-25 | 35             | 39             | 25         | P1315.25-F |
| P1316.32-36-20 | 32             | 36             | 20         | P1315.30-A |
| P1316.45-50-20 | 45             | 50             | 20         | P1315.30-B |
| P1316.32-34-25 | 30             | 34             | 25         | P1315.30-C |
| P1316.45-50-25 | 45             | 50             | 25         | P1315.30-D |
| P1316.32-36-30 | 32             | 36             | 30         | P1315.30-E |
| P1316.45-50-30 | 45             | 50             | 30         | P1315.30-F |
| P1316.40-44-25 | 40             | 44             | 25         | P1315.40-A |
| P1316.60-65-25 | 60             | 65             | 25         | P1315.40-B |
| P1316.40-44-30 | 40             | 44             | 30         | P1315.40-C |
| P1316.60-65-30 | 60             | 65             | 30         | P1315.40-D |
| P1316.40-44-40 | 40             | 44             | 40         | P1315.40-E |
| P1316.60-65-40 | 60             | 65             | 40         | P1315.40-F |
| P1316.50-55-30 | 50             | 55             | 30         | P1315.50-A |
| P1316.75-80-30 | 75             | 80             | 30         | P1315.50-B |
| P1316.50-55-40 | 50             | 55             | 40         | P1315.50-C |
| P1316.75-80-40 | 75             | 80             | 40         | P1315.50-D |
| P1316.50-55-50 | 50             | 55             | 50         | P1315.50-E |
| P1316.75-80-50 | 75             | 80             | 50         | P1315.50-F |



| Order No.        | d <sub>1</sub> | d <sub>2</sub> | l<br>±0.25 | For spring |
|------------------|----------------|----------------|------------|------------|
| P1316.100-105-40 | 100            | 105            | 40         | P1315.60-B |
| P1316.60-65-50   | 60             | 65             | 50         | P1315.60-C |
| P1316.100-105-50 | 100            | 105            | 50         | P1315.60-D |
| P1316.60-65-60   | 60             | 65             | 60         | P1315.60-E |
| P1316.100-105-60 | 100            | 105            | 60         | P1315.60-F |